ORDER FOR SUPPLIES OR SERVICES

(Contractor must submit four copies of invoice.)

Form Approved OMB No. 0704-0187 Expires Jun 30, 1997 PAGE 1 OF

Public reporting burden for this collection of information is estimated to average 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Department of Defense, Washington Headquarters Services, Directorate for Information Operations and Reports, 1215 Jefferson Davis Highway, Suite 1204, Arlington, VA 22202-4302, and to the Office of Management and Budget, Paperwork Reduction Project (0704-0187). Washington, DC 20503.

PLEASE DO NOT RETURN YOUR FORM TO EITHER OF THESE ADDRESSES. SEND YOUR COMPLETED FORM TO THE PROCUREMENT OFFICIAL IDENTIFIED IN ITEM 6. 4. REQUISITION/PURCH REQUEST NO. 5 PRIORITY 3. DATE OF ORDER (YYMMMDD) 1. CONTRACT/PURCH ORDER NO. 2. DELIVERY ORDER NO. F34601-00-G-0006 YPC03343000284 **UBFZ** 2004 MAR 23 DOA1 CODE 7. ADMINISTERED BY (If other than 6) CODE 6. ISSUED BY SP0700 S2207A 8. DELIVERY FOB **Defense Supply Center Columbus** DCMA GE LYNN 3990 E.Broad St. P.O. Box 16704 DEST 1000 WESTERN AVE Columbus,OH 43216-5010 LYNN MA 01910-0445 OTHER X Local Administrator: PAABCAC (614)692-7512 / FAX: (614)692-5269 E-mail: Dorinda.Conner@dla.mil CRITICALITY: C (See Schedule if other) II. MARK IF BUSINESS 10. DELIVER TO FOB POINT BY(Date)
(YYMMMDD) 272 DANG ADD 9. CONTRACTOR FACILITY CODE CODE 99207 373 DAYS ARO 12. DISCOUNT TERMS GENERAL ELECTRIC COMPANY DIV GENERA ELECTRIC AIRCRAFT ENGINES SMALL DISAD-VANTAGED NAME AND ADDRESS 1000 WESTERN AVENUE NET 30 days WOMEN-OWNED LYNN MA 01910 13. MAIL INVOICES TO Vendor's Copy was sent EDI. Do not Duplicate shipment. See Block 15 14. SHIP TO 15. PAYMENT WILL BE MADE BY HO0337 CODE CODE MARK ALL HO0337 DFAS COLUMBUS CENTER See Schedule - Do Not Ship to Address in Block 6 PACKAGES AND NORTH ENTITLEMENT OPERATIONS PAPERS WITH P O BOX 182266 CONTRACT OR COLUMBUS OH 43218-2266 ORDER NUMBER EFT: T This delivery order is issued on another Government agency or in accordance with and subject to terms and conditions of above numbered contract DELIVERY X TYPE offer dated 2004 FEB 24, C 04TQ169 and furnish the following on terms specified herein. OF PURCHASE ACCEPTANCE. THE CONTRACTOR HEREBY ACCEPTS THE OFFER REPRESENTED BY THE NUMBERED PURCHASE ORDER AS IT MAY PREVIOUSLY HAVE BEEN OR IS NOW MODIFIED, SUBJECT TO ALL OF THE TERMS AND CONDITIONS SET FORTH, AND AGREES TO PERFORM THE SAME. RDER NAME OF CONTRACTOR SIGNATURE TYPED NAME AND TITLE DATE SIGNED (YYMMMDD) If this box is marked, supplier must sign Acceptance and return the following number of copies: 17. ACCOUNTING AND APPROPRIATION DATA/LOCAL USE CG: 97X4930 5CC0 001 26.0 S33150 97X4930 5CC0 001 22.1 S33150 (TRANS) QUANTITY ORDERED/ ACCEPTED* 18. ITEM NO. 21. UNIT UNIT PRICE AMOUNT SCHEDULE OF SUPPLIES/SERVICE Remarks: CONFIRMING ORDER – DO NOT DUPLICATE ACCELERATED DELIVERY IS ACCEPTABLE AND DESIRED AT NO COST TO THE GOVERNMENT. TOTAL: 24. UNITED STATES OF AMERICA 17556.70 25. TOTAL If quantity accepted by the Government is same as quantity ordered, indicate by X. If different, enter actual quantity accepted below quantity ordered and CONTRACTING/ORDERING 79 BY DIFFERENCE 28. D.O. VOUCHER NO. 26 OUANTITY IN COLUMN 20 HAS BEEN 27. SHIP. NO. 30. ACCEPTED, AND CONFORMS TO THE CONTRACT EXCEPT AS NOTED RECEIVED 32. PAID BY 33. AMOUNT VERIFIED CORRECT FOR PARTIAL FINAL 34. CHECK NUMBER 31 PAYMENT SIGNATURE OF AUTHORIZED GOVERNMENT REPRESENTATIVE DATE 36. I certify this account is correct and proper for payment COMPLETE 35. BILL OF LADING NO. PARTIAL SIGNATURE AND TITLE OF CERTIFYING OFFICER DATE FINAL 40 TOTAL CONTAINERS | 41 S/R ACCOUNT NUMBER 42. S/R VOUCHER NO. 37.RECEIVED AT | 38. RECEIVED BY (Print) 39. DATE RECEIVED (YYMMMDD)

	Order Number:	PAGE	OF	PAGES
CONTINUATION SHEET	F34601-00-G-0006-UBFZ	: ا	2	3

SECTION B

PR YPC03343000284 NSN 3020-00-151-7581

ITEM DESCRIPTION:

GEAR CLUSTER.

CRITICAL APPLICATION ITEM

GENERAL ELECTRIC COMPANY DIV GENERA (99207) P/N 5017T31G01 GENERAL ELECTRIC COMPANY DIV GENERA (99207) P/N 5019T31P01

<u>ITEM PR PRLI QUANTITY UNIT UNIT PRICE AMOUNT</u>

0001 YPC03343000284 0001 5 EA <u>\$3511.34000</u> <u>\$17556.70</u>

QTY VARIANCE: PLUS 0%

MINUS 09

INSPECTION POINT: ORIGIN ACCEPTANCE POINT: ORIGIN

PREP FOR DELIVERY

PKGING DATA - MIL-STD-2073-1D, 15 DEC 1999

QUP = 001: PRES MTHD = 31: CLNG/DRY = 1: PRESV MAT = 00:

WRAP MAT = GB: CUSH/DUNN MAT = XX: CUSH/DUNN THKNESS = X:

UNIT CONT = D3: OPI = O:

INTRMDTE CONT = D0: INTRMDTE CONT QTY = AAA:

PACK CODE = U:

MARKING SHALL BE IN ACCORDANCE WITH MIL-STD-129.

SPECIAL MARKING CODE: 00 - NO SPECIAL MARKING.

PALLETIZATION SHALL BE IN ACCORDANCE WITH DC1636P001 REV E

DATED 3029

For all shipments of packaged materiel to the government, which includes either depot (DLA-direct) or DVD (customer-direct) shipments, both DoD linear and 2-D bar code markings are required on military shipping labels in accordance with MIL-STD-129, revision P, dated December 15, 2002, as amended by Change Notice 1, dated January 15, 2004. 2-D bar coding shall be in accordance with ISO/IEC 15438, ISO/IEC 15434 (ANSI MH10.8.3) and DoD 4500.9-R. MSL linear (code 3 of 9 or code 39) bar coding shall be in accordance with ISO/IEC 16388. MSL label stock quality shall meet MIL-PRF-61002. MSL bar code print quality

CONTINUED ON NEXT PAGE

F34601-00-G-0006-UBFZ

PAGE OF PAGES

1

SECTION B

shall meet ANSI MH10.8-2000 or ANSI X3.182-1990 (R2000) for applicable 2-D and/or linear bar codes. All DVD shipments shall meet additional linear bar coding requirements in DLAD 52.211-9008. When the contract/order omits any data element required to be bar-coded, the field shall be zero-filled. These requirements do not apply to delivery orders when the basic contract has not been modified to require MIL-STD-129P. If there are inconsistencies between the schedule and MIL-STD-129P, the schedule takes precedence.

DELIVER FOB: ORIGIN BY: 2005 MAR 31

PARCEL POST ADDRESS:

W25G1U
XU TRANSPORTATION OFFICER
DDSP NEW CUMBERLAND FACILITY
BUILDING MISSION DOOR 113 134
NEW CUMBERLAND PA 17070-5001

FREIGHT SHIPPING ADDRESS:

W25G1U
TRANSPORTATION OFFICER
DDSP NEW CUMBERLAND FACILITY
BUILDING MISSION DOOR 113-134
NEW CUMBERLAND PA 17070-5001

NON-MILSTRIP PROJ NS1

REMIT PAYMENT TO:



DEFENSE LOGISTICS AGENCY

DEFENSE SUPPLY CENTER COLUMBUS POST OFFICE BOX 3990 COLUMBUS, OHIO 43216-5000

PRODUCT QUALITY DEFICIENCY REPORT / REQUEST FOR INVESTIGATION

Date: March 17, 2004

1. Category: 2

2. DSCC Report Control Numbers: C04065023

3. Originator: DSCC

4. Customers Report Control Numbers:

5. Date Deficiency Discovered: 3/04

6. NSN: 3040-01-488-9290

7. Nomenclature: Carriage cylinder

8. Manufacturer: Columbus Equipment Company Inc.

65 E. Kingston Ave.

Columbus, Oh 43207-2436

9. Manufacturers Part Numbers: 50001197

10. Serial/Lot/Batch No:

11. Contract Numbers: SP0740-03V-L662

12. New/Repaired/Overhauled: New

13. Date Recvd, Mfrd, Repaired or Overhauled:

14. Operating Time at Failure: Not Applicable

15. Government Furnished Material:

16. Quantity: A. Received: 2

B. Inspected: 2

C. Defective: 2

- 17. Defective item works on or with:
 - A. End Item:
 - B. Next Higher Assembly:
- 18. Unit Cost: \$ 540.90
- 19. Estimated Repair Cost: Unknown
- 20. Item Under Warranty:
- 21. Work Unit Code:
- 22. Action/Disposition: Holding Exhibit For: 90 days
- 23. Details: Customer stated that "part received was the wrong item. Part number received 50001196 (NSN 3040-01-488-9289). Customer states item is forked on one end with 2 points that stick out."
- 24. Request that Contractor investigate this complaint for conditions contributing to the cause and initiation of corrective measures to preclude shipment of items with like or similar discrepancies. Request contractor notify QAS below on or before **March 23, 2004** to initiate investigation of this issue.
- 25. If an exhibit is desired, please advise as soon as possible. Request every effort be extended to expedite this investigation. The request should include shipping instructions and specify a "Mark For" designee. If a request for exhibit is not received within 30 calendar days, we request an interim reply with explanations.
- 26. Request that we be advised of the results of the investigation and corrective measures taken by both the contractor and the Government Representative (if applicable) before **April 23, 2004.**
 - In the event that contractor responsibility is determined, please include recommended disposition instructions together with the contractors position regarding replacement or repair of material at no cost to the Government.
- 27. The POC for this Report of Discrepancy (ROD) is Cheryl Abercrombie-Beckett, QAS, DSN: 850-1690, Commercial: (614) 692-1690, Fax: (614) 692-3734 or Email: Cheryl_Abercrombie-Beckett@dscc.dla.mil.